GOVERNMENT OF ANDHRA PRADESH $\underline{ ABSTRACT}$

Public Servants – Roads & Buildings Department – Disciplinary proceedings initiated against Sri A.Venugoapal, the then Assistant Executive Engineer (R&B), Markapur (now working as Assistant Executive Engineer (R&B), Section, Kakumanu, Tenali Division), as he failed to monitor/supervise properly the work of construction of ROB at Rayavaram Village of Guntur-Nandyal Section and R&B Road of Podili-Markapur Road in Prakasam District – Penalty of stoppage of 2(Two) increments without cumulative effect - Orders – Issued.

TRANSPORT, ROADS & BUILDINS (VIG.I) DEPARTMENT

G.O.Rt.No. 231

Dated.02-03-2012. Read the following:-

- 1) From the Engineer-in-Chief (R&B), Admn., & N.H., A.P., Hyderabad Lr. No. 284/VC(6)/2010, dt. 08.03.2010.
- 2) Memo.No.284/VC(6)/2010-3, dt.08.03.2010 of the Engineer-in-Chief (R&B), Admn., & N.H., A.P., Hyderabad.
- 3) From Sri A. Venugoapal, Assistant Executive Engineer (R&B) Section, Markapur representation dated 29.05.2010.
- 4) From the G.A.(V&E) Department Vigilance Report No.8 (437)/V&E/E2/2010), dt. 24.01.2011.
- 5) Govt. Memo. No. 2451/VIG.I(1)/2010-5, dt. 02.07.2011,
- 6) From the Engineer-in-Chief (R&B), Admn., & N.H., A.P., Hyderabad Lr. No. 284/VC(6)/2010, dt. 24.08.2011.

ORDER:

Article of charge was issued in the reference 2nd read above, to Sri A.Venugoapal, the then Assistant Executive Engineer (R&B), Markapur (now working as Assistant Executive Engineer (R&B), Section, Kakumanu, Tenali Division), as he failed to monitor/supervise properly the work of Construction of ROB at Rayavaram Village, in lieu of L.C.No.236 at Railway Km.143/10-12 of Guntur-Nandyal Section and R&B Road at K.M.37.2 of Podili-Markapur Road in Prakasam District, due to which 13 slabs of ROB are executed with deficit reinforcement.

- 2. Sri A. Venugoapal, the then Assistant Executive Engineer (R&B), in the reference 3rd read above has submitted his representation denying the charge; and, requested that he may kindly be exonerated from the charge, and to drop further action against him; and, the explanation is not convincing.
- 3. Government, after careful examination of the matter, observe that there was confusion/lack of understanding regarding the drawing, by Sri A. Venugoapal, Assistant Executive Engineer (R&B), and that is clear professional failure; and, hence decide and hereby impose the penalty of stoppage of 2 (two) increments without cumulative effect against him, in respect of work of failure to monitor/supervise properly the work of construction of ROB at Rayavaram Village, in lieu of L.C.No.236 at Railway Km. 143/10-12 of Guntur-Nandyal Section and R&B Road at K.M.37.2 of Podili- Markapur Road in Prakasam District.
- 4. The Engineer-in-Chief (R&B), Administration shall take further necessary action accordingly.

(BY ORDER AND IN THE NAME OF THE GOVERNOR OF ANDHRA PRADESH)

S.P.SINGH PRINCIPAL SECRETARY TO GOVERNMENT

Tc

Sri A. Venugoapal, Assistant Executive Engineer (R&B), **through** the Engineer-in-Chief (R&B) Administration & N.H., A.P., Hyderabad.

The Engineer-in-Chief (R&B), Administration & N.H., A.P., Hyderabad.

Copy to:

The Secretary, Andhra Pradesh Vigilance Commission Hyderabad.

The General Administration (V&E) Department, BRK Bhavan, Hyderabad. SF/SC.

//FORWARDED::BY ORDER//